# Municipal Environmental Associates, Inc.

Consulting Engineers
Finore Building — Bethlehem Pike
P. O. Box 627
Spring House, Penna. 19477
Phone 215 628-2973

March 10, 1982

U.S. Environmental Protection Agency 6th & Walnut Streets Philadelphia, PA 19106

Re: East Coast Chemical Disposal, Inc. Permit Application Your letter of March 3, 1982

Attn: Gil Horwitz

Gentlemen:

Part "A" Application is amended as per your request and is enclosed.

Part "B" information has been answered and is on file with EPA. See the following:

- 1. Section 122.25 (a) General Information (See page AD 1 to 4 and Appendix 1 & 2)
- 2. Contingency Plan Local agencies listed on C-2. PA - DER is contacting these agencies.

Section 122.25 (b) Specific Information Requirements (A) (B) (C) (D) are found on PP-4 and I-2, (E) PP-4, B-3, D-8, C-2. (ii) Pages I-3, Appendix 2 and 3, B7 and 8; (iii) Page I-3.

Section 122.29 RCRA Permit Conditions - Page PP-4 Appendix 2 and 3.

Should you have further questions, please call.

Sincerely yours,

Miles B. Potter, P.E.

MBP/fr Encl.

cc: East Coast Chemical Disposal, Inc.

The amended PR4 To Make it easter to find pumps.

260,000

3

T 0 4

U

0

10

### III Facility Layout - Details

Each storage area is designed to hold a maximum of 144 drums of 50 gallon capacity (Appendix 2 and 3). Floors for the storage area slope at a rate of 1/8 inch per foot to a spill retention basin of 96 cubic feet. Drums will sit on a four (4) inch high pallet type platform. Storage areas will be diked using 8" x 8" x 16" concrete block.

The concrete floor of the facility will be coated with a prime coat of an H-B Epoxy and a final coat of Epoxy Enamel.

Compressive strength of this six (6) inch floor is thought to be in excess of 3,500 psi, since it is designed for heavy equipment.

Tools and materials will have an area of 600 square feet while the treatment area will have 780 square feet.

All storage areas have a minimum of 50 foot buffer on all sides.

Sump pumps and/or vacuum pump will remove and prevent overflow of spill retention basins.

⁄unic	cipal Enviro	onmer	ntal Asociates, Inc.	LE'	TTEK-OF TRANSMITTA
o	P. Spring 4	. O. Box	627 nna. 19477 973	OATE 44	1/23/8~ 3100 Gil Horwitz ast Coast Chemical Disposal
	Ph. Idelp		Streets PA 19186		
GENTI	EMEN:				. /
•	WE ARE SEI  ☐ Shop draw	wings	□ Prints □ P □ Change order □ Under separ	Plans	/
PIES	DATE	NO.		DESCRIPTION	
/	4/20/82		Part B - Keusson to	is page	73-8
THESE	ARE TRANSMIT	TED as c	hecked below:		
			☐ Furnish as submitte	ed [	Revise and Resubmit
	☐ For your	use	□ Furnish as correcte	. <b>d</b> [	□ Submit specified item
-	As reques	sted	□ Rejected	[	Returncorrected prints
	☐ For review	w and com	ment 🗆		
DEMA	ove Added	Naro	graph 265.18 7	Treitmei	7
KEMA	KN3	$\rho_{\omega}$	1		
		· · · · · · · · · · · · · · · · · · ·			
			***************************************	<del></del>	
				· · · · · · · · · · · · · · · · · · ·	
COPY	TO FCC	S Pil	<i>i</i>		
FORM				SIGNED:	Miles B Potter
· URIV	000			-	

If enclosures are not as noted, kindly notify us at once.

be employed in all the processes of either the shop area or the loading and receiving area. Incoming wastes that are more than slightly acid or basic will be neutralized immediately upon unloading. Wastes which appear to be highly ignitable will be treated prior to entering the facility and special treatment may also be applied immediately upon reception as well. Treatment at the facility involves solidifying the waste through the addition of fly ash and vermiculite. This treatment also reduces the probability of any reactions. The present wastes received by ECCD appear to be quite compatible for comingling and do not give off uncontrolled toxic mists.

### 265.18 Treatment (Processing) Area

The treatment of wastes will be done in a 780 square foot floor area covered with a layer of Quick-Dri or vermiculite. Processing is generally described in 265.1 and in 265.13 through 265.17.

This floor area of 780 square feet is large enough to locate automated equipment as deemed necessary.

Any spills or leaks in this area will be cleaned up according to specifications as outlined in 265.56IA.


# Municipal Environmental, sociates, Inc.

# LETTER OF TRANSMITTAL

Finore Building - Bethlehem Pike P. O. Box 627 Spring House, Penna. 19477 215-628-2973 **GENTLEMEN:** WE ARE SENDING YOU Attached Under separate cover via\_ \_\_\_the following items: □ Prints □ Plans □ Samples □ Specifications ☐ Shop drawings □ Copy of letter □ Change order THESE ARE TRANSMITTED as checked below: ☐ Furnish as submitted Revise and Resubmit ☐ Furnish as corrected ☐ Submit specified item ☐ For your use ☐ Return \_\_\_\_\_corrected prints ☐ Rejected ☐ As requested ☐ For review and comment D \_\_\_\_\_ REMARKS Sending fine (5) Ropies to DER


FORM 006

If enclosures are not as noted, kindly notify u



Revised 5/5/82 Appendix No. 3

and it states



Revised 5/5/82 Appendix No. 3

# LETTER OF TRANSMITTAL Municipal Environmental Associates, Inc. Finore Building - Bethlehem Pike P. O. Box 627 Spring House, Penna. 19477 215-628-2973 **GENTLEMEN:** WE ARE SENDING YOU □ Attached □ Under separate cover via\_ \_the following items: □ Shop drawings □ Prints □ Plans □ Samples □ Specifications □ Copy of letter □ Change order THESE ARE TRANSMITTED as checked below: □ Furnish as submitted Revise and Resubmit ☐ For your use □ Furnish as corrected ☐ Submit specified item As requested ☐ Rejected ☐ Return \_\_\_\_\_corrected prints □ For review and comment 51/2 - Enclosed entire Map - Should you prefer

COPY TO ECCD File

SIGNED: TILES 13. POTTEY

11 enclosures are not as noted, kindly notify us at once.

### APPENDIX I

Intergency coordinator		
Dan Tarrats	Office:	
	Home: 201/343-	6699
	Page-beeper:_	
Other qualified acting Emergenc	y Coordinators	•
D. Gandy	Office:	
	Home:	
	Page-beeper:_	
L. Connelly	Office:	
<u> </u>	Home:	
	Page-beeper:_	
Other important numbers, ECCD,	Inc. personnel	•
Name: Phil Einhorn	Office:	
Title: Chemist	Home: 215/674	-8259
Name: M.B.Potter	Office:215/62	8-2973
Title:Consulting Engineer	Home: 215/441	-0577
Name:	Office:	
Title:	Home:	
Edgely Fire Company & Ambulance Services Bristol Township Police Bucks County Emergency Dept. of Transportation (Common Environmental Protection Agency PA Dept. of Environmental Resou PA Dept. of Health Bucks County Health Department Chemtrec Emergency Response Num	wealth)(DOT) (EPA) rces (DER)	215/943-1200 215/949-2000 215/547-5222 717/787-7445 215/597-9800 717/787-4526 717/787/6436 215/343-2800 800/424-9300

## APPENDIX I

Emergency Coordinator		
Dan Tarrats	Office:	
	Home: 201/343-	-6699
	_ Page-beeper:	
Other qualified acting Emerger	ncy Coordinators	5.
D. Gandy	Office:	
	<u>_</u>	
L. Connelly	Office:	•
·		
Other important numbers, ECCD		
Name: Phil Einhorn	Office:	
Title: Chemist	Home: 215/67	1-8259
Name: M.B.Potter	Office:215/62	28-2973
Title:Consulting Engineer	Home: 215/44	L-0577
Name:	Office:	
Title:	Home:	
Edgely Fire Company & Ambuland Services Bristol Township Police Bucks County Emergency Dept. of Transportation (Common Environmental Protection Agency PA Dept. of Environmental Resorvation PA Dept. of Health Bucks County Health Department Chemtrec Emergency Response No.	onwealth)(DOT) cy (EPA) ources (DER)	215/943-1200 215/949-2000 215/547-5222 717/787-7445 215/597-9800 717/787-4526 717/787/6436 215/343-2800 800/424-9300

EAST COAST CHEMICAL DISPOSAL, INC. Levittown, Bucks County Pennsylvania

Addendum No. 1 to 265.13 Waste Analysis Plan

RCRA PERMIT APPLICATION
for
Hazardous Waste
Part B.
Storage and Treatment
40 CFR Parts 122, 264 - thru 265

Project No. 3100

February, 1982

Prepared By

Municipal Environmental Associates, Inc.
908 Bethlehem Pike Finore Building
Spring House, Pennsylvania

#### SUBPART B

### GENERAL FACILITY STANDARDS

### 265.13 Waste Analysis Plan

As described above, all wastes received for processing and subsequent disposal are classified as hazardous wastes. Accordingly, a rather extensive analysis plan will be required to ensure that

- 1. All wastes received are what were contracted for.
- 2. Quality control is maintained through out the entire processing operation.

East Coast Chemical Disposal, Inc. has established a policy that will require each waste generator to CERTIFY that the wastes shipped to ECCD will NOT contain any of the products found on a list of unacceptable materials. This list includes but is not limited to

Pesticides.

Carcinogenic materials - known and suspected.

Polychlorinated biphenyls (PCB's).

Radioactive materials.

Poisons.

This list is constantly reviewed, based on current literature and is updated and/or changed as necessary.

The generator certification eliminates the need for testing for all of these materials.

A. Initial sample/contact interview.

When a prospective customer requests that a sample be submitted for evaluation, a field sales engineer is sent out to interview the customer to obtain a sample, and, if possible, to observe the process actually generating the waste.

Appendix 1 represents a typical contact interview questionnaire. The questionnaire form is self-explanatory but several items need to be discussed further.

- 1. Waste identification this is what the customer or generator calls the waste, not what the sales engineer perceives it to be.
- 2. Process description the most important feature of the questionnaire is the detail relating to the process generating the waste. ECCD will

sign the appropriate confidential agreement with a waste generator, if necessary, to obtain this information.

3. Remarks - here the sales engineer writes the actual identification of the waste stream; analytical information supplied by generator may be entered here.

The routing of this questionnaire will be as follows:
Original - white - general manager.

2nd copy - canary - lab.

3rd copy - pink - transporation.

4th copy - blue - sales.

Representative samples of potential waste streams are very important but, unfortunately, are difficult to obtain. Bulk wastes may be sampled using a Bacon Bomb thief's sampler (somewhat messy, but effective). Drums, on the other hand, MUST be individually sampled. The fancy name for this type of sampler is the COLIWASSA but a stout thumb and a pipe will do exceptionally well.

## B. Laboratory Analysis.

All samples submitted to ECCD for evaluation and pricing for potential recycling and/or disposal will receive the following minimal lab analysis:

Specific gravity.

Flash point (Tag Closed Cup or Pensky Martins Closed Cup)

Total residue on evaporation.

Distillation range and yield.

Component identification and concentrations.

It should be noted that component composition and concentration will be determined by using a gas chromatograph with a flame ionization detector.

Based on the contact interview questionnaire, additional testing may be required. Testing beyond our capabilities will be sent to an outside laboratory.

C. Laboratory Analysis - PA DER Requirements
The Pennsylvania Department of Environmental Resources requires that all hazardous or residual waste streams be submitted for approval prior to treatment, storage or disposal at a TSD facility. This request is made using the Module 1 application (Appendix 2). An extensive laboratory analysis, in addition to that

listed above, is required when submitting a Module 1. However, in order to respond to the waste generator in a timely manner, the Module 1, complete with the additional analysis, will be submitted only after a firm order is issued by the waste generator.

It should be noted that the generator is actually responsible for initiating the Module 1 submittal, but ECCD may do so as a service to the generator.

### D. Receipt Control.

When a quotation is issued to a waste generator for a specific waste stream, specifications for the waste are provided. Before the waste stream arrives at the ECCD facility, these specifications are entered on a Treatment-Spec sheet for the plant and laboratory.

Upon arrival, the load (if bulk) is sampled and is submitted to the laboratory for analysis. If the waste arrives in drums, each drum is sampled and the appropriate composites are made.

When the analysis is complete, a determination is made whether the waste load is "in spec or out of spec". If in spec the load is accepted for processing. If "out of spec", the waste generator is notified immediately by telephone. The final disposition of the "out of spec" load then rests with the generator.

At a minimum, all incoming loads will be analyzed as in Section B above.

All loads will be "logged in" several ways. A master log will be kept by the laboratory denoting the following information:

Date.

Time of Arrival.
Trailer Number.
Waste Generator.
Waste Identification.
Manifest Number.
B/L Number.
Disposition of Load.
Remarks.

A second log will be kept by the waste generator and by the office staff. This log will include the appropriate analytical data in addition to the data kept on the master log, as described above.

# EAST COAST CHEMICAL DISPOSAL, INC. CONTACT INTERVIEW QUESTIONNAIRE

# APPENDIX 1

Gene	eral			
	erator Name			
Fac	ility Address	G	enerator EPA #	
Bus	iness Contact:			
245.				
	Title		Phone	
	· · · · · · · · · · · · · · · · · · ·			
Tecl	hnical Contact:			
			<b>7.</b>	
	-		Phone	
Was	te Description			
1.	Generator's common	name for	this waste stream.	
2.	Process Generating	Waste:		
3.	Generation Rate		Frequency	

Physical Properties (Circle appropriate blocks)	5. Chemical Co	omposition	
Physical State at 70°F:     Solid    Semi-Solid    Liquid    Sludge    Gas	Analysis (Account for 100%)	Constituent	Range
2. Specific Gravity	1	Water	
3. Flash Point °F Closed Cup Open Cup			
4. Viscosity: Low Medium High	2	Major	
5. pH (Indicate Range)	<del></del>		
6. Phase / Layering (For liquids only)			
NONE BILAYERED MULTILAYERED			
Top% Others%	· <del></del>		
Bottom%%			
7. Solids:   By Weight   By Volume	3	Minor	
Total % Dissolved % Suspended %			
8. Solvents & Oils Only	· ·		
BTU/ Lb Ash Content @ 650 °C			
9. Organo-Chlorine: O-TR ◄1% ►1%			
10. Sulfur: O-TR			

## EAST COAST CHEMICAL DISPOSAL, INC.

### PA DER MODULE 1

## APPENDIX 2

Waste Generator:
Waste Identification:
W/C Lab Code:

Test Parameter	Total Analysis	ElP Leachate
Total Residue Total Dissolved Solids Total Volatile Solids pH Cyanides		·
Oil and Grease Ammonia N Phenol Arsenic Antimony		
Barium Cadmium Chromium Lead Mercury		
Nickel Selenium Silver Copper Molybdenum		
Zinc		

Heating Value Ignitability Corrosivity Reactivity Total Organic Halogens COD TOC

Analysis completed by:

Date:

DATE	PREPARED
DATE	REVISED

### PA DEPARTMENT OF ENVIRONMENTAL RESOURCES BUREAU OF SOLID WASTE MANAGEMENT MODULE 1

				•
DEPARTMENT	USE	ONLY		_

REQUEST FOR APPROVAL TO TREAT, STORE, OR DISPOSE OF A HAZARDOUS OR RESIDUAL WASTE STREAM

SEE	INST	RUCTI	IONS BEFORE COMPLETING THIS FORM
١.	GE	NER	AL INFORMATION (must be completed by TSD facility)
	A.	Tre	eatment, Storage, or Disposal Site
		1.	Name of facility
			Address
			Municipality County
		2.	Identification number (if applicable)
		3.	Solid waste permit number(s) for treatment, storage or disposal facility to be utilized
		4.	Facility contact person
			Name Title
			Phone no.
	В.	Ger	nerator of the Waste
		1.	Name of company
			Mailing address
			Location of site if different from mailing address
			Municipality County
		2.	If a subsidiary, name of parent co.
		3.	Identification number (if applicable)
		4.	Company contact person
			Name title

וווח			

DATE PREPARED	
DATE REVISED	

9.

D	EPA	RTM	ENT	USE	ONLY	,		
-								
							-	

II. WASTE DESCRIPTION (Must be completed by Generator)

1.	pH range		to		(based	on past	analyse	es or kno	owiedge)
2.	Physical	state:							
	a. 🗆	liquid (less dry wt. or	than 20% solids flowable)	by c.				or great d non-flo	
	<b>b.</b> 🗆	gas (ambien pressure)	t temperature an	d d.					was chec liquids.
3.	Physical	appearance:							
	Color			Odd	r				
			iquid phases of						
õ			of separation				_		
	2 333.133	, p							
4.	U.S. DO	Γ proper shi <sub>l</sub>	oping name UN/	NA numbe	er, and	i hazard	class (i	f applica	ble):
4.	U.S. DO	Γ proper shi <sub>l</sub>	oping name UN/	NA numbe	er, and	d hazard	class (i	f applica	ble):
<b>4. 5.</b>			oping name UN/						
	Typical v	volume of wa		ed to treat	ment	storage			
	Typical v	olume of wa	aste to be shippe	ed to treat	ment (circl	storage			
5.	Typical va. Mon	volume of watching thing the control of the control	aste to be shippe	ed to treat gal., tons gal., ton	ment (circl	storage le one) cle one)	or dispo	osal facili	ity:
5.	Typical va. Mondo. Anno Treatment va.	thly t or disposal	aste to be shippe	ed to treat gal., tons gal., ton	ment (circles (circ	storage le one) cle one) nes per y	or dispo	osal facili	ity: ne
<ol> <li>6.</li> </ol>	Typical value of the second of	thly t or disposal volume to be (circle one)	frequency:	gal., tons gal., tons atment sto	cment (circles (circ time rage o	storage le one) cle one) nes per y	or dispo year; □	osal facili	ity: ne

Has the waste been delisted as a hazardous waste by DER?  $\Box$  Yes  $\Box$  No  $\Box$  N/A

If yes or N/A, check the appropriate box(es) in Item 10.

DATE	PREPARED	
DATE	REVISED	

DEPARTMENT	USE	ONLY	

_	ded commercial chemical product		process waste
□ off-sp	ecification species		infectious waste
-			baghouse dust
☐ manu	acturing chemical intermediate		wastewater treatment plan residue (industrial)
□ still be	ottom		
☐ spent	catalyst		wastewater treatment plant residue (sewage)
☐ flyash			water treatment plant residue
□ botto	n ash		incinerator residue
			acid mine drainage treatment sludge
☐ slag			spill residue
☐ found	ry sand		
	crubber sludge	. 🗆	other (specify)

- B. Chemical Analyses Please attach the following:
  - 1. The results of the total analysis of the waste as described in the instructions.
  - 2. The results of the leaching tests as described in the instructions and the leaching method.
  - 3. A description of the sampling method.
  - 4. The range of concentrations of the constituents based on knowledge or past analyses.
- C. Process Description and Schematic Please attach the following:
  - 1. The substantiation for a confidentiality claim as described in the instructions, if portions of the information you have submitted are confidential.
  - A detailed description of the manufacturing and/or pollution control processes producing the hazardous or residual waste as specified in the instructions.
  - 3. A schematic of the manufacturing and/or pollution control processes producing the hazardous or residual waste as specified in the instructions.
- III. Liner Compatibility Evaluation (must be completed by TSD facility)

Attach the results of the liner compatibility evaluation or supporting data as specified in the instructions.

	. <u></u>				•					DEPAR	TMEN	NT USE	ONL	Y	
V.		OPOSED To facility.						POSAL N	1ETHOD	) (must	be	comp	leted	by	
	A.	Proposed	Treatme	ent Metho	ď										
						, e									
	В.	Proposed	Storage	Method	and Lei	ngth of	Storage								
	,														
										. •					
	C.	Proposed	Disposal	Method											
														•	
<b>'.</b>		TERNATIV generator.						OR DIS	POSAL	METH	OD	must	be o	qmo	lete
	Α.	What Oth Briefly do							mation	Method	i(s)	Can b	e Us	ed?	

B. Why was the Treatment and/or Disposal Method in Section IV Chosen?

DATE PREPARED	MODILLE A DAGE E	
	MODULE 1, PAGE 5	
DATE REVISED		FOR DEPARTMENT USE ONLY
VI. CERTIFICATION OF	CENEDATOR	
I certify under penalty this and all attached docu obtaining the information	of law that I have personally examined and auments, and that based upon my inquiry of the I believe that the submitted information is truities for submitting false information, including the	ese individuals immediately responsible for use, accurate and complete. I am aware that
Name of Responsible Official		Title
Signature		Date
Taken, sworn and subscribed b	sfore me, this	
NOTARY SEAL	day of A.O. 19	
/II. CERTIFICATION OF AND/OR DISPOSAL I	REGISTERED PROFESSIONAL ENGINE FACILITY	EER FOR TREATMENT STORAGE
This is to certify that modules, drawings, specific it to be of good engineer Department of Environme	I have personally reviewed all engineering informations, and other documents which are part of ing quality, true and correct, and is in conformatal Resources, and it does not, to the best of the ermination of compliance with the requirements	this application and that I have found nance with the requirements of the my knowledge, withhold information
NOTICE: It is an offense to the Department.	under Pennsylvania Crimes Code to affirm a fa	alse statement in documents submitted
Name		:
_		
Address		SEAL OF PA REGISTERED

Phone No.

PROFESSIONAL ENGINEER

ER-SWM 59:1/82

# PENNSYLVMA DEPARTMENT OF ENVIRONMENTAL RESURCES BUREAU OF SOLID WASTE MANAGEMENT

### HAZARDOUS WASTE PERMIT APPLICATION - PART A

Please print or type in the unshaded areas only

the provided the p	·		
I. EPA I.D. NUMBER		J. British Company	the second of the second of the second
PAD 9 80 7 06 16 2			
II. NAME OF FACILITY	· 医二种原义或此种原则 的		Secretary Secretary
East Coast Chemical Disposal, Inc.			
III. FACILITY CONTACT		Barrell Commence	mile a marginal despring from the property of
A. NAME & TITLE (last, first, & title)			HONE (area code & no.)
Rex A. Hunter, Cert. Hazardous Mate	rials Manager	2 1	5 5 7 5 1 8 8 0
IV. FACILITY MAILING ADDRESS	ggar Bergaragerye ya katika ji jawa jigat	e filmente verberen, etc	at Pharing in Street, 1975, in
A, STREET OR P.O. I	3QX		
c/o R.A.H. CONSULTING, 295 W. Stree		9	
8. CITY OR TOWN	4 .		C, State D, Zip Code
Warminster	·.		P A 18 9 7 4
A. STREET, HOUTE NO. OR OTHER SPECIFIC ID	ENTIFIER -	E. MUI	HCIPALITY
201 E. Tenth Street		Marcus Hook	
B. CITY OR TOWN	×	p Code F. C	OUNTY
Marcus Hook	P A 18	974 Delaware	
VI. SIC CODES (4-digit, in order of priority)	***************************************		
A. FIRST	(specify)	C, THIRD	
B, SECOND	(specify)	D. FOURTH	
		pagarang and pagarang pagarang and and an	one and any one stage and the dealership Mar
A. NAM		Stellie V. A. Stellie V. St. Stellie St.	B, is the name listed in
			Item VII -A size the
East Coast Chemical Disposal, Inc.		/	✓ YES   ✓ NO
C; STREET	OR P.O. BOX		
N. Washington Avenue	. :		
D. CITY OR TOWN	E, State F	, Zip Code G. P	HONE (area code & no.)
Bergenfield	סונא	762120	1 3 8 5 7 9 0 3
H. STATUS OF OPERATOR (Enter the appropriate letter into	the answer box; if "Other", spe	cify.)	
F = FEDERAL M = PUBLIC (other than federal or state) S = STATE 0 = OTHER (specify) P = PRIVATE	- New Color		
VIII. EXISTING ENVIRONMENTAL PROGRAM PERMITS		CARLON CONTRACTOR	and a property of the
A. NPDES (Discharges to Surface Water) D. PSD (Air Emissions fro	m Proposed Sources)		
B. UIC (Underground Injection of Fluids) E. SOLID W	ASTE		
NAIIIII			
C. RCRA (Hazardous Wastes) F. OTHE	,R (speci	fy)	
IX. MAP	ella deleta per en en en	中華的學術學學學	Control Service Services
Attach to this application a topographic map of the area extending	to at least one mile bound	proporty boundaries	The man must character

outline of the facility, the location of each of its existing and proposed intake and discharge structures, each of its hazardous waste treatment, storage, or disposal facilities, and any well where it injects fluids underground. Include all springs, rivers and other surface water bodies in the map area as per the instructions.

		Year Control of the C			
	OF BUSINESS (provide a				1.00
· ·		es, both liquid			
II.	•	inator (manufact			
		to an enclosed			
f		waste is transpo			
1	` <i>.</i>	disposal facilit		nid solvents ar	re
***************************************	taken to solver REVISED APPLICATIO	nt recovery facil	ities.		·
Place on "X" in t	the appropriate box in A or B Son, if this is your first applic	below (merk one box only) to it action and you already know you	ndicate whether this is the	first application you are sub	mitting for your facility or lication, enter your facility's
A- EIRST APPLI	CATION (place an "X" below	a and provide the appropriate da	(e)	T 2 NEW PACIFIES	(Complete item below.)
		G FACILITIES, PROVIDE THE		IVE MOCIDAY	FOR NEW FACILITIES.
	tuse the boxes		RUCTION COMMENCED	85 10 01	TION BEGAN OR IS EX- PECTED TO BEGIN
200000000000000 <del>0000000000000000000000</del>	PLICATION (place on "X" b Histy has interim stat	ilaw and complete Section () TUS		2. FACILITY HAS	A BCRA PERMIT
		GN CAPACITIES 🔀			ئۇغىرلىيىغ يەكسىلىنىڭ ئىنىڭلىنىڭ ئىرى ئا
entering code	s. If more lines are needed, ar	is list of process codes below the ter the code(s) in the space pro- pacity) in the space provided on	ided. If a process will be	ess to be used at the facility, used that is not included in t	Ten lines are provided for he list of codes below, then
B. PROCESS DE		code entered in column A ente		ESE.	
2. UNIT OF	MEASURE - For each amou	nt entered in column B(1), enter e that are listed below rrey be u	the code from the list of	unit measure godes below th	at describes the unit of
	PRO- CESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS		CESS MI	PROPRIATE UNITS OF ASURE FOR PROCESS
STORAGE: Container (barrel Tank		DESIGN CAPACITY  Gallons or Liters	PROCESS TREATMENT: Tank		SIGN CAPACITY  llons Per Day or
Tank Waste Pile Surface Impound	\$03	Gallons or Liters Gallons or Liters Cubic Yards or Cubic Meters Gallons or Liters	Surface Impoundment	TO2 Ga	ers Per Day llons Per Day or ers Per Day
DISPOSAL: Injection Well	279	Gallons on Liters	Indineratos	Per	ns Per Hour or Metric Tons Hour; Gallons Per Hour or ers Per Hour
Landfill	D80	Acre Feet (the volume that smould cover one sare to a depth of one foot) or	Other (Use for physica thermal or biological t	il, chemical, TO4 Ga reatment Lit	llons Per Day or ers Per Day
Land Application Onean Disposal	1 D81 D82	Hectars-Meter Acres or Hectares Gallons Per Day or	processes not occurring surface impoundments ators. Describe the pro-	, or inciner cesses in	
Surface Impound	Iment D88 UNIT O	Liters Per-Day Gallons or Liters	I the space provided (its	Alicij	UNIT OF
OF MEAS		Unit of measur		INIT OF MEASURE	MEASURE CODE
Liters Cubic Yards	GIRCD	Liters Per Day Tons Per Hour Metric Tons Per Ho Gallons Per Hour	D W	ore-Feet Soture-Meter ores	, 8
Gallons Per Day	ti i i i i i i i i i i i i i i i i i i	Liters Per Hour		enteres	. · ·
EXAMPLE ***	EGD GOARD CTILL COLOR		Approximation of the second		and the same of the same
	the other can hold 400 p	XII (shown in line numbers ) ellons. The facility also has a	n incinerator that can b	facility has two storage ta urn up to 20 gallons per	nks, one tank can hold hour:
14 770 0	n bhactar is action	T. 000		D. DROCKES DUSIEW CO.	a comv
A. PRO- CESS CODE (from	B. PROCESS DESIGN CA	2. UNIT OFFICIAL USE		B. PROCESS DESIGN CAL	2. UNIT OFFICIAL OF MEA- USE
(tst above)	(menty)	SURE ONLY	(from list above)	1. 7.200.1	SUBE ONLY (enter code)
V. al.al.al	202	code)	<del>                                     </del>		
X-1 S 0 2	600	G	5	····	<del></del>
X-2 T 0 3	- 20	E	6		<del></del>
1 5 01	130,000	· G	7		
2 T O 4	5,000		8		
3			9		
			10 11		
4	•				

### XII. PROCESSES (continued)

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESSES (code "704"), FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY;

A treatment Received wastes will be treated in containers. regime will be established as part of the pre-acceptance testing of each waste. Treatments to be utilized will be both Physical treatment will consist of physical and chemical. stabilizing and solidifying sludges and absoprtion of free liquids. Chemical treatment will consist of any or all of neutralization, oxidation-reduction, cyanide destruction, and dissolved metals precipitation. Final disposal will occur off-site at permitted land disposal facilities or incinerators. Solvents which have commercial value will be readied for off-site reclamation by solvent recovery facilities.

### DESCRIPTION OF HAZARDOUS WASTES

- HAZARDOUS WASTE NUMBER Enter the four-digit number from 75.261(h) for each listed hazardous waste you will handle. If you handle hezardous westes which are not listed in 75.261(h), enter the lour-digit number(a) from 75.261(g) that describes the characteristics and/or the EP toxic contaminants of those hazardous westes.
- ESTIMATED ANNUAL CHANTITY For each listed waste entered in column A estimate the quantity of that waste that will handled on an annual basis. For each characteristic on EP toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant,
- UNIT OF MEASURE -- For each quantity entered in column B enter the unit of measure code, Units of measure which must be used and the appropriate codes are:

	E	Ņ	ķ	•	L	Ş	4	l	ŧ	1	(1	T	•	H	ķ	ı	ú	ķ	į	J	R	E	×					ζ	ζ	ij	)	E					ŧ	4	E	T	R	k		t	IN	ı	۲	¢	ı	×	v	E	A	\$	U	R	E							×		1	3	9	D	Ε	
				j i																																889	800	99		99			***	***		S	***	***	***		***	9.9	***	~~	***			200	988		883	***	**	100	Τ.	 	9	**			

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the wests.

### D. PROCESSES

PROCESS CODES!

For listed hezardous waster. For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Section XII to indicate how the waste will be stored, treated, and/or disposed of at the facility For non-listed hazardous wastes: For each characteristic or EP toxic contaminant entered in column A, select the code/s/ from the list of process codes contained in Section XII to Indicate s// the processes that will be used to store; treat, and/or dispose of all the non-listed hazardous wastes that possess the characteristic or toxic contaminent.

Note: Four spaces are provided for entering process codes, if more are needed; (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item XIII-D(1); and (3) Enter in the space provided on page 5, the line number and the additional

will be in a landfill.

PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE HAZARDOUS WASTE NUMBER -- Hazardous wastes that can be described

by more than one Hazardous Waste Number shall be described on the form as follows:

1. Select one of the Hazardous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating

the total annual quantity of the weste and describing all the processes to be used to treat, store, and/or dispose of the waste.

2. In column A of the next line enter the other Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.

3. Repeat step 2 for each other Hazardous Wasta Number that can be used to describe the hazardous wasts.

EXAMPLE FOR COMPLETING SECTION XIII (Shown in line numbers X-1, X-2, X-3, and X-4 below) — A facility will treat and dispose of an estimated 900 pounds per year of leaded tank bottoms from the petroleum refining industry. In addition, the facility will treat and dispose of the non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal

M . HAZARD	B ESTIMATED ANNUAL	G UNIT	D. P	ROCESSES
HAZARD. MASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	SURE (enter code)	. 1. PROCESS CODES (enter)	2. PROCESS DESCRIPTION (if a node is not entered in D(1))
X-1 K 0 5 2	900	P	03 080	
X-2 D 0 D 2	400	ρ	r o 3 o 8 o	
X-3 D 0 0 1	100	P	T 0 3 D 8 D	
X-4 D 0 D 2				"Included with above"

Hard, Waste No. Genter code:    A	Tion n D(1)
1 D601 S0,000 PS01 T04	
2 DO 02 50,000 SO 1 TO 4	
	Į.
3   Molay   10,000   1.   \S   0   1   0   4   1   1   1   1	
	<del>-</del>
7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
DOU9 10,000   SO1704	
9 1010 10,000 1501704	
10 POI 1 10,000 SOITOY	
11 DO12 10,000 1 SO1704	
12 DU13 10,000 SO1704	
13 DOIY 1000 SOITOY	
14 DUIS 10,000 / SOITOY	
15 DO16 10,000 1501704	
DU17 10,000   501704	
17 FOOI 10,000 KOITO4	
18 FOOZ 10,000 - 501704	
20 F0 0 7 10,000 S01704	
21 FOOR 10,000 'SOITOY	
22 FOOG 10,000 - SO1704	
23 FOIO 10,000 SOIT04	
24 F0 1 2 10,000 1 501 T04	
25 F019 (C,000) S01704	
26 KOOI 10,000 PSD1704	

XIII. DESCRIPTION OF HAZARDOUS WA	STES (continued)	and the second of the second o
		D. PROCESSES
Harard QUANTITY OF WASTE	G. UNIT OF MEA SURE (enter (enter) (enter)	2. PROCESS DESCRIPTION (If a code is not entered in D(1))
1 K002 10,000	PS01704	
2 K003 10,000	PS01704	
3 2004 10,000	1 PS01704	
4 KO 03 10,000	PS01704	
5 K006 10,000	1. PS 01 TO 4	
6 K007 10,000	PS01704	
7 K008 10,000	1 PS01704	
10,000	1. PS01704	
9 KOII 10,000	1/PS01704	
10 KO13 10,000	PS01704	
11 KO14 10,000	PS01704	
12 KOIS 10,000	PS01T04	
13 2016 10,000	PS01704	
14 K017' 10,000	PS01704	
15 KO 18 10,000	PS01704	
1019 10,000	PS01704	
17 K 020 10,000	PSOITOY	
18 10 21 10,000	PS01704	
19 K 0 2 Z 10,000	PS01T04	**
20 KOZ3 10,000	PS01704	
21 K 0 2 4 10,000	PS01704	
22 2025 10,000	PS01704	
23 10 26 10,000	PS01704	
24 KUZP 10,000	1, PS01704	·
25 K029 10,000	PS01704	
26 6030 10,000.	PSO ITO4	
	PAGE 4 A DE 6	

PAGE 4 A OF 8

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

30000000	D	ES	CF		ION OF HAZARDOUS WAS B. ESTIMATED ANNUAL QUANTITY OF WASTE	C.	UNI	T ×	ıue	d)					>	2				D. PROCESSES
LINE NO.	We Cerr	lez ete ter			QUANTITY OF WASTE		ME URI Inter ode				1	. [	'n¢	)CE (en	35 (er)	co	DE	S		2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	K	٥	3	)	10,000	P		S	٥	i	ī	C	,	1	I	I	I	T		
2	K	0	ζ	2	10.000	D		S	٥	1	7	C	) 4	1						
3	K	٥	3	3	10,000	Þ		S	٥	1	7	0	i	1						·
4	K	O	7	Y	10,000	P	,	S	٥	1	7	10	اد	1						
5	Ľ	0	3	2	10,000	P		s	0	1	7	C	راد	{	$\perp$	$\perp$	1	$\perp$		
6	K	O	3	6	16,000 .	P	-	S	0	1	7	0	4	4	$\perp$		1	1		
<b>7</b>	Ľ	٥	3	7	10,000	P		S	0	1	17	0	4	4			1			
ح ح	۲	0	3	8	10,000	Þ		3	٥	1	7	Q	1	1	1		1			
9	K	O	3	9	(0,000	P		S	٥	1	17	0	١١	1	$\perp$		1	Ŀ	$\perp$	
10	۲	ø	ч	0	10,000	D	·	S	0	L	7	0	14	1	$\perp$	$\perp$	1			
11	K	O	५	1	10,000	ρ		ß	٥	1	1	0	14	4	$\perp$	$\perp$	$\perp$			
12	۲	0	4	2	10,000	P	, ,	s	0	1	7	0	اد	1						
13	K	S	Y	8	10,000	Þ	į	S	٥	1	7	0	4		$\perp$	1	1			
14	K	0	4	9	10,000	P		2	0	1	7	0	14	4	$\perp$		$\perp$	Ŀ		
15	K	၁	5	0	10,000	Δ		ς	٥	1	Ī	c	ار	1						
	K	0	S	1	(0,000	þ		2	٥	1	7	0	اد	1			1			
17	K	0	5	2	10,000	P	,	2,	٥	1	Ī	10		1		1				
18	K	٥	6	0	10,000	9		2	0	1	17	c	اد	1	$\perp$	$\perp$	1	1	$\perp$	
19	K	٥	6	2	10,000	P		ß	0	l	Ī	0	) (	1		$\perp$		1		
20	K	0	6	1	/o, 000	P	ŀ	2	0	ŀ	7	10	اد	f	1	1			1	
21	K	ú	6	9	. 10,000	P	<u>\</u>	2	0	L	7	10		1	1	1	1	1		
22	2	ပ	7	1	(0,000	P		3	0	1	17	(	اد	4		$\downarrow$	1	1		
23	K	b	7	3	(0,000	P		3	╌	+-	7			4	1	1	$\perp$	1		
24	K	0	8	3	10,000	P		2	0	1	17		3/4	4	1	1	1	1	1	
25	K	0	8	4	(0,000	P		S	O	1	Ī	10	2	1	1	1	1	1	1	;
26	·K	C	8	5	14,000	P	7	S	0	1		-	ار مار							

PAGE 4 B OF

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

33334333		*****		_	TION OF HAZARDOUS WA B. ESTIMATED ANNUAL QUANTITY OF WASTE		S (co		ıue	d)						>: 						D. PROCESSES
LINE NO.	W.	A lazi sto tor			QUANTITY OF WASIE	1	URE inter ode)					. P	R	0¢	ES nte	S C	:01	)E.	3			2. FROCESS DESCRIPTION (if a code is not entered in D(1))
1	K	O	8	6	10,000	P		Š	0	li	l	0	4	4				T	T	1		
2	K	0	P	7	10.000	P		S	0	1	7	10	0	4				T	T			
3	K	S	9	3	10,000	P		S	0	1	1	0	1	4								
4	K	0	9	4	10,000	P		S	6	1	7	0		4								
5	K	O	٩	5	000,00	P		ς	٥	I	-	10		4								
6	K	0	9	6	10,000 .	P	•	S	٥	1	7	-	ŀ	4								
7	K	Ó	q		(0,000	P		3	٥	1	1	10	de	4								
* - '8	K	O	9	જ	(0,000	P	1	5	٥	1	1	10		4								
9	K	0	4	3	10,000	P		S	0	1	1		1	4			L					
10	K	٥	9	9	10,000	P	·	5	0	1	Ŀ	10		4		L	L					
11	K	0	2	7	10,000	P		S	٥	1	1	10		4		L	L	$\perp$				
12	K	0	1	0	10,000	P		2	٥	1	1		1	4			L					
13.	۲	1	0	0	10,000	P		5	o	1	ŀ	70	1	4		L	L	1				
14	K	1	0	1	10,000	P		2	0	L	j	10	1	4			L	1				
15	K	1	Ó	2	10,000	P	•	Ş	0	1	Ŀ	10	1	4			L		1			
3	K	1	0	3	10,000	P	· .]	\$	٥	1	ŀ	de	1	4		L	L					
17	K	١	٥	4	10,000	P		\$	o	1	-	10	1	4		L	L					
18	K	1	0	7	(0 000	P		3	٥	1	ŀ		1	4		L		1	ŀ			
19	K	1	0	6	10.000	P		2	0	1	ľ	10	1	4		L	L	1			_	·
20	F	0	1	0	5.000	P		S	0	1	į	10		५		L	L	1	1		_	
21	P	0	1	1	2.900	P		2	0	1	þ	10		4	L	L	L	1	1		_	
22	P	ပ	1	2	000,2	þ.		S	C	1	1		2	4	L	L		1				
23	P	0	1	3	5,0∞	Þ		S	0	1			2	4	L						_	
24	P	0	7	0	5,000	P		5	þ	1	İ		2	4	L							
25	F	0	2	9	2.0∞	P		2	þ	1	1	1	2	4	L		1	1	1	_		
26	P	0	5	1	5,000	P		S	C	1	1		0	4								

PAGE 4 \_C\_ OF 6

20000000000	E	ES	C	RIP	TION OF HAZARDOUS WA B. ESTIMATED ANNUAL QUANTITY OF WASTE	TI C	S (cc Unii Me)	ntii	nue	d)					>:					D. PROCESSES
LINE NO.		ia: asti		o. de	400000000000000000000000000000000000000		URE enter rode)					Pl	101	CP: ent	iS C er)	:01	)ES			2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	P	0	S	9	5.000	P		Ś	0	1	7	0	4							
2	F	0	01	O	5,000	0	,	S	0	~	7	0	4		Ŀ					
3	9	٥	6	3	5,000	P	,	S	0	-	7	0	4							
4	P	٥	S	5	5,0∞	P		S	O	1	7	٥	4							
5	4	o	-	4	5,000	٩	,	2	0	١	7	٥	4							
6	7	o	8	9	5,000	۹		S	0	1	7	٥	4	L	L					
7	1-	O	9	8	5,000	٦		S	0	1	7	o	4			L		L		
-8	P	0	9	9	5,000	P		S	0	١	7	٥	4					Ŀ		
9	P	i	O	4	5,000	7		S	٥	1	.7	0	4	L				L		
10	2	1	ပ	6	5,000	P		S	0	-	7	٥	4		L	L				
11	12	1	ı	0	5,000	A		s	0	1	7	0	4			L				
12	F	1	1	2	5,000	P		s	0	1	7	0	4				L			
13	P	1	2	6	5,000	P	-	2	0	١	T	0	ч							
14	P	1	2	1	2.000	P	4	ς	٥	1	ī	0	4	ŀ		L		ŀ		
15	P	0	9	4	5,000	P		5	0	1	7	٥	4		L			L		
3	U	0	c	2	/0,000	þ	Ш	5	0	1	7	0	4							
17	U	c	1	3	10,000	13		S	0	1	7	0	4							
18	نا	0	1	9	10,000	P		2	0	١	Ī	0	4					Ŀ		
19	u	0	3	1	10, 000	P	(	ς	٥	1	7	0	4							•••
20	U	9	13	12	10,000	P		2	0	ı	7	0	4		L	L				
21	V	U	3	6	10,000	12		2	0	1	7	0	4	L			1	$\downarrow$	$\downarrow$	
22	U	U	?	17	10,000	P	Ц	S	0	1	ī	0	4			1	1	1	1	
23	U	C	4	3	10,000	P		2	0	1	7	0	4				1			
24	U	O	١	14	10,000	P		S	٥	!	T	0	4				$\perp$		1	
25	U	ر	4	12	10,000	P		S	٥	1	Ī	0	4	1	_	1	1	1	$\downarrow$	
26	U	C	) (	(8	10,000	p		S	٥	1.	7	0	4							<u> </u>

PAGEA D DER

NOTE: Photocopy this page before completing if you have more than 26 westes to list.

*****				1P1	TION OF HAZARDOUS WAS B. ESTIMATED ANNUAL QUANTITY OF WASTE	TE	S (co	ontir F	ıue	d)						>2	4				D. PROCESSES
LINE NO.			ard N	00000 I	QUANTITI OF WASTE	G G	UNI ME URE inter ode)				1	. Р	RC	CE (en	23 S uter	Ç	OD.	ES			2. PROCESS DESCRIPTION (If a code is not entered in D(1))
1	9	0	2	,	5,000	P	•	S	6	1	7	D	ļ	1							·
2	U	ပ	2	1	10,000	P	Ċ	S	0	1	7	0	4	1							
3	U	ပ	5	2	10,000	P		2	٥	1	7	٥	4	4	1		_				
4	U	၁	Ø	4	10,000	وا		2	0	1	7	0	4	1					L	L	
5	C	C	5	6	(0,000	P	,	S	0	1	7	0	4	4	1		_			L	<u> </u>
6	J	٥	G	1	10,000 .	P		S	o	1	7	0	4	4	1				L	L	
7	Ċ	0	Q	5	10,000	P		S	0	1	7	6	4	4	1				L	L	
	V	υ	6	7	10,000	P		S	ပ	1	7	ن	14	4					Ŀ	L	
9	Ú	O	6	8	10,000	P	1	2	0	Ŀ	17	0	4	4	1		_		Ŀ	L	
10	v	o	7	0	(0,000	Р		2	٥	1	T	0	ľ	1	1				L	L	
11	U	0	7	1	10,000	P	4	S	0	1	7	0	١	4	1				L		•
12	U	0	7	2	(0,000	P		S	0	1	7	0	1	4	1				L	L	
13	U	o	1	⋖	(0,000	P		2	o	1	7	O	1	1	1					L	
14	U	0	7	6	10,000	P		S	0	1	1	0	4	4				L	Ŀ		
15	U	0	1	7	10,000	P		2	Ó	1	7	0	1	4					L		
;	U	0	8	0	10,000	P		S	Ö	l	7	6	L	4	1		_	L			
17	V	υ	9	1	(0,0∞	P	Li	5	ပ	Ŀ	17	٥	4	1				L	L		
18	U	0	8	2	10,000	P		S	0	1	7	c	ا	4			L		Ŀ	L	
19	U	1	1	2	(0,000	P	5	5	0	1	17	10	1	4	_			L	L	_	
20	U	1	2	1	10,000	P		5	6	1	1		1	4	1		L	L			
21	U	1	1-	2		P	1-1	3	0	1	Т		7	_	4		Ŀ	L			<u>.</u>
22	V	1	2	3	10,000	P	Ц	2	0	1	7	0	1	4		_	L	L	L		
23	1	1	2	17	10,000	P	\. <i></i>	2	0	1	1	0	1	1				L		_	
24	U	1	7	4	10,000	P		+	0	۲	┿	0	┿	4				L	L	$\downarrow$	
25	L	业	7	0	10,000	P		2	0	1	Ī	c	1	4	_		L	L		-	
26	·	1	١	4	10,000	P	1.1	S	_		GE	7	٠.	4							

PAGE 4 F OF 6


(enter "A", "B", "C", etc. behind the "4" to identify photocopied named


					ION OF HAZARDOUS WAS	π.	S (co				 				<b>&gt;</b>					the book of the self of the se
LINK.		A 14 2 51 0	****	2000	B. ESTIMATED ANNUAL QUANTITY OF WASTE	Sec.	UNIT MPA URE Inter ode)					P	RO	OE.	95 (	201	DES			D. PROCESSES  2. PROCESS DESCRIPTION
1					16		ode)	·V		·	Γ	Γ	Γ	T	T	T	T	T	T	2 PROCESS DESCRIPTION (if a code is not entered in D(1))
	2	4	प	3	10,000	0	4	S	П	-	7	T	T	╀	╁	┞	╀	╀	┞	
2	Ч	1	2	4	(0,000	A	1	S	Ó	_	H	0	4	╀	1	┞	+	-	┞	
3	U	1	3	겍	10,000	٥	-	3	_		7	1	1	╀	$\downarrow$	-	$\downarrow$	╀	-	
4	U	1	5	9	16,000	P		3		~	7	0	4	Ļ	$\downarrow$	Ļ	1	$\downarrow$	L	
5	U	1	ઉ	1	10,000	P		S	٥	1	7	O	4		$\perp$	L	$\downarrow$	$\perp$	L	
6	U	1	6	5	10,000 .	٦		2	0	1	7	0	4	1	$\perp$	L	$\downarrow$	$\perp$	L	
.7	Ú	1	8	2	14,000	P		ડ	O	-	7	0	4	L		L			L	
projektor.	U	1	8	8	10,000	P		2	٥	1	7	0	4					Ŀ		
9	U	2	0	ч	(0,000	Ρ	-	ς	٥	-	7	0	4							
10	U	2	0	Ş	10,000	P	,	S	O	1	7	0	4	Γ	Τ	Γ	T	Γ		
11	U	Z	O	9	(0,000	P		S	٥	1	7	O	4	T		T	T		T	•
12	U	2		0	10,000	Þ		5	0	,	7	c	4							
13	U	2	~	1	(0,000	P	i.	S	0	ı	7	0	4							
14	U	2	Ξ	4	10,000	P		5	٥	1	7	c	4	Ŀ				Ŀ	L	
15	U	2	1	5	10,000	P		2	٥	1	7	0	4							
16	U	2	. =	G	10,000	٩		5	0	,	7	0	4							
17	v	2	_	7	10,000	P		2	0	1	1	0	4							
18	ľ	2	7	0	(୦,୭୪୬	P	1	5	0	1	7	٥	4							
19	U	2	2	7	(0,000	þ	3.	2	0		7	0	4							
20	U	2	2	5	10,000	P	Ģ.	5	0	1	7	0	4							
21	v	ک	2	C	(0,000	P		5	٥	1	7	0	4					L	L	
22	U	2	2	7	10,000	Þ		S	0	1	7	٥	4							• •
23	v	2	2	8	(0,000	P	7	5	0	ı	7	0	4							
24	U	2	2	9		P	<i>(</i> ,	ς	٥	1	7	C	4							
25	Т	Г	Г	o	(0,000	P		s	o	1	7	0	4							Í
26	Г	2	Г	1	(0,000	P		s	0	1	7	0	4							


XIII		ES A lazi	CF ird	ilP	B. ESTIMATED ANNUAL QUANTITY OF WASTE	TE Co		oni T	_		1					S C					D. PROCESSES  2. PROCESS DESCRIPTION (If a code is not entered in D(1))
1	IJ	2	3	3	10,000	P	,	. 6	s	J		,	٥	4							·
2	U	2	3	8		٥		Ş	3 (	5	1	7	٥	4		·					
3	V	2	3	9	10,000	Þ	,	4	3 0		1		0	ч							·
4	F	0	1		10,000	a	:	ļ	s	, 1	1	7	٥	4							
5								1		1	$\perp$										·
6								1	1	1	1	1			Ц						
7			_					$\downarrow$	1	1	1	1					_				
ີ ບໍ່ ———			_					1	$\downarrow$	1	1	1					_				
9								4	$\downarrow$	1	1	_					_		Ŀ	L	
10		Ŀ	Ĺ					4	1	1	1	1	_				_	L	_	_	
11			_				$\sqcup$	4	+	+	1	4	_		_		_		_	L	•
12	_		L			L	H	$\downarrow$	$\downarrow$	4	4	4	_	_	_		L	L	L	L	
13		_	_	-		_		4	$\downarrow$	+	4	+	_		_	_	L	-	_	_	
14		L	_	-	-	-		4	+	$\downarrow$	4	-		_	L	_	L	-	ŀ	_	
15	_	-	L	-		ŀ	$\sqcup$	+	+	+	+	+	_	_	-	L	L	L	L	_	
Theres, or	L	L	-	-		ŀ	H	+	+	+	+	4	_	L	$\vdash$	-	-		-	L	
17	-	-	L	╀		-	H	+	+	+	+	+	_	_	$\vdash$	-	$\vdash$	-	_	_	
18 19	-	-	┞	╀		-		+	+	+	+	-	_	-	-	├	$\vdash$	$\vdash$	-	-	i
	$\vdash$	$\vdash$	$\vdash$	╁		┞	Н	+	+	+	+	+	_	-	-	-	-	├	-	-	
20: 21	H	$\vdash$	$\vdash$	-		-	Н	+	+	+	+	+	_	$\vdash$	-	-	$\vdash$	$\vdash$	-	$\vdash$	
22	-	$\vdash$	-	$\vdash$	and the state of t	1	H	+	$\dagger$	+	+	+		-	-	-	-	-	$\vdash$	-	
23	-	-	+	+		-		+	$\dagger$	+	+	+		-	-	-	-	$\vdash$	-	-	
24	+	-	-	+		-	H	+	+	$\dagger$	+	-	-	-	-	-	+	T	-	+	
25	-	<b> </b>	t	$\dagger$		-	H	+	+	+	+	-		-	$\vdash$	1	1	+	-	-	
26	+	+	1	$\dagger$		1	H	1	+	+	1	1	_		1	$\dagger$	T	1			·
	L	ــــــــــــــــــــــــــــــــــــــ	Ļ	_		1_					<u></u>	_	. /	L		 F 6	<u>L</u>		<u></u>	<u></u>	I

PAGE 4 6 OF 6


KIII. DESCRIPTION OF HAZARDOUS WASTE  E. USE THIS SPACE TO LIST ADDITIONAL PROCES	30000000000000000000000000000000000000		•
		7	•
		•	
•			
•			
	•		
		•	
			·
# # * * * * * * * * * * * * * * * * * *			•
•	•		
XIV. FACILITY DRAWING	•		
All extering facilities must include in the space provided of XV PHGTOGRAPHS::		-	
All extering teclibres must include photographs (serie) or areas; and alrea of future storage, treatment, or deposal se	ground-level) that clearly dalinests all ax reas (set instructions for more detail).	sting structures; existing storage, tr	setment, and dispose
XVI. FACILITY GEOGRAPHIC LOCATION  LATITUDE (degrees, minutes) & seco	> ;	LONGITUDE (degrees, minutes), (	
3947 06		752500	
XVII. FAGILITY OWNER > 1			
A if the facility owner is not the facility operator  B. If the facility owner is not the facility operator			on XVIII below.
	anisted at Section 21, complete the folia	owing (terms)	
L. NAME OF FACE	CATT'S LEGAL OWNER	2. PHQ)	NE NO. (area pode & ng.)
3. STREET OF F.D. BOX			
	4. CITY OR TOWN	5. ST.	6. ZIF CODE
XVIII. GWNER CERTIFICATION	<b>&gt;</b> V		
I cartify under penalty of law that I have personally documents, and that based on my inquiry of those a submitted information is true accounts.	inciviculais irompriistoliv mennineihio		
submitted information is true, accurate, and comple metuding the possibility of fine and imprisonment.	ets. I am awere that there are signific	cant penalties for submitting fal	se information,
A. NAME (print or type).	B. SIGNATURE	C.DATES	GNED
Lewis Maslow	Leus vaslar	7/18/	85
XIX: OPERATOR CERTIFICATION  I certify under penelty of law that I have personally  foruments and that haved as	examined port are families with the		
submitted information is true, accurate, and comple	INDIVICALISTS INTRACTISTOLS FOR NAME AND A		
- s are performed to the and management.		and penalues for summining fall	at Pitormation,
A NAME (print pr type) Lewis Maslow ,	Leuis marlar	G DATESI	*********
	Heuis Marlan	7/19/8	5










South Side

















- North Side

CONTINUED FROM THE FRONT	emonas a na symme sametra no no no se na entro y estructares.	and the second s	and the commentation is a section of the section of	Antidomentus i sagan galat tepidemidan kurus sa sa sa sagan galat dalah kurusan an as sa
V.A. SIC CODES Segret in order of priority)	. :		B. SECO	ND .
7 P001 to P122 Commercial Chemical	ls 7 U		specify)	hemicals-Intermedi
C. THIRD			D. FOUR	тн
(specify)	15	1	specify)	
K002 to K069 Organic Chemicals	1 13	<del>001-t</del> b	F016 Non-spe	ecific Sources
8 Mark Beinart	NAME	adressadous de la como de la		Item VIII-A also the owner?  YES X NO
13 16	-	<del></del>	<del></del>	56 66
C. STATUS OF OPERATOR (Enter the appropriate letter in				D. PHONE (area code & no.)
F = FEDERAL M = PUBLIC (other than federal or state) S = STATE O = OTHER (specify) P = PRIVATE	P (specify)	ivate		15 628 2973
E. STREET OR P.O. BOX	<del></del>			
			5	
F. CITY OR TOWN		G.STATE	H. ZIP CODE IX, INDI.	- the state of the
B Hook	, , , , ,			ility located on Indian lands?
I Marcus Toca			52	YES X NO
X. E ING ENVIRONMENTAL PERMITS	40	41 42 47	The state of the s	
A Santana in the contract of t	ir Emissions from P	roposed Sou	rces)	The rest of the second
CITIE TO THE CITIES	1111		TT	
9 N 9 P	N/A		30	·
B. UIC (Underground Injection of Fluids)	E. OTHER (speci	fy)		
9 U N/A 9	N/A .		(specify)	
13 16 17 18 - 30 15 16 17 18  C. RCRA (Hazardous Wastes)	E. OTHER (speci	£.:	30	
GILL TITTE TO GILL	1 1 1 1 1	7.57 	(specify)	
9 R 9 N/A 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	N/A		-1-1-30	
Attach to this application a topographic map of the area enthe outline of the facility, the location of each of its exist treatment, storage, or disposal facilities, and each well was water bodies in the map area. See instructions for precise re	ting and propose here it injects flu	d intake ar	nd discharge structures	s, each of its hazardous waste
XII. NATURE OF BUSINESS (provide a brief description)	anta anta in santa penggangan sanggan taga anta sanggan sa	Control and		
Industrial wastws, bo	th liquid	and se	emi-solid are	
picked up from an ori				
and transported to an		•	_	
ment. After treatment				
certified hauler to a liquid solvents are t		_		
XIII, CERTIFICATION (see instructions)	nada nada kanada ka	بعدد دورد المالك المستعدد		richard and the state of the st
I certify under penalty of law that I have personally exametrachments and that, based on my inquiry of those peapplication, I believe that the information is true, accurate false information, including the possibility of fine and important the personal personal including the personal personal including the personal personal including the personal personal including the personal	rsons immediatel te and complete.	y responsit	ble for obtaining the l	information contained in the
A. NAME & OFFICIAL TITLE (type or print)	B. SIGNATURE	4		C. DATE SIGNED
Lewis Maslow, CEO	Lem	shias	lon.	8/20/182
COMMENTS FOR OFFICIAL USE ONLY	and a state of the	An application process		of the second
C				

Please (fill—	e pri <i>in चा</i>	nt or eas a	type in the unsh re spaced for elit	te type, i.e., 12 characte	ALALON CO. PROPERTY. STATE AND ADDRESS.	Committee (In 1845)	SA STRUME OF BRIDGE SHARING		D'INNE ANNOUS.	ar waan	FILM		d OMB N	A CONTRACTOR OF THE	\$800 <b>0</b>	4 	Maran
FO											A I.D. NUMBER						ed;
3	1	6.9		(This informa	Consolida	ted Per	unis Pro	oram			F						-
FOR		FIC	IAL USE ONL	Y at the second process and second process.							at Windowski	Carried Co. and				وال ومر	ė.
APPL	IC.	VED	(yr, mo., & c								MENTS						
II. F	IRS	TO	R REVISED A	PPLICATION	and the specific of the same	and deed		g <b>samp</b> instru La conferencia				en programme Recommenden		menn a se		7 50 19 04 14 14 1	
revise	d ap	plica	n the appropriate stion. If this is year ober in Item I abo	e box in A or B below (a our first application and ove.	mark one bo you alread	<i>x only</i> y know	/ to indi v your fa	cate v	nether	this	is the first application	on you a	re submit	ting for	your i	acilit	y or .: .ity's
A. F	IRS	T A	PPLICATION	(place an "X" below an ITY (See inst≔ctions fo Complete item bel	d provide the r definition ow.)	e appro of "ex	opriate o isting" f	late) acility.			2.N	EW FAC	ILITY (C	omplete FOR N PROVI	EW F	ACIL	SALTE
c 8	73		MO. DAY	FOR EXISTING FACI OPERATION BEGAN (use the boxes to the le	OR THE 07 (t)	ATE C	ONSTRU	ЈСТІО	yr., mo N COM	., & i	day) NCED    R   2   73   74	1 2	DAY 1 1 77 78	(yr., mo	o., & d Bega	ay) o n or	PERA IS
B. R	-	ISE	APPLICATIO	ON (place an "X" belou ITERIM STATUS			m I abou	ie)			∏a. <b>r</b>	ACILIT	Y HAS A	RCRA	PERM	IT	
***	72					1/A	and the second			<b>V</b>	- 12		A CANADA				•
				S AND DESIGN CAL		Sin was	الاستونسونيي المصطفييي	and de	ooribos	ANOUNCE NO. O. O.	process to be used	at the fa	cility Ta	n lines s	re or	vider	t for
e e	nteri	na co	des. If more line	the code from the list of es are needed, enter the ding its design capacity)	code(s) in t	he spac	ce provid	led. If	a proc	ess w	vill be used that is no	ot includ	ed in the	list of co	odes b	elow,	then
B. P	Δ!	MOLI	NT - Foter the:	CITY - For each code e											•		
( )	U	NIT (	OF MEASURE -	- For each amount enter e units of measure that a	ed in colum	n B(1)	, enter ti	he cod	e from	the !	list of unit measure	codes be	low that d	lescribes	s the u	nit of	f
	111	easur	e used. Only the	PRO- APPRO	RIATE UN	ITS O	F	iscu.				PRO-		PRIAT			
		P	ROCESS		RE FOR PF IGN CAPA(		S			PRC	CESS	CESS MEASURE FOR PROCESS					
Sto	rage								tment:	_							
TA	ΝK		R (barrel, drum,	S02 GALLON	S OR LITE S OR LITE			TAN				T01	GALLO	PERD	ΑY		
i		PIL	E MPOUNDMENT	CUBIC M	ARDS OR ETERS 5 OR LITE	RS			PACE NERA		DUNDMENT	T02	LITERS PER DAY				
	pos		MPOONDMENT	SU4 GALLON	JON LIVE			11107			•		METRIC	TONS NS PER	PER	нου	R; ₹
IN.	EC.	TION	WELL	D79 GALLON D80 ACRE-FE	S OR LITE ET (the vol	RS ume th	ıat	отн	ER (U	e fo	r physical, chemical,	т04	GALLO			OR	
	ACRE-FEET (the volume that would cover one acre to a depth of one foot) OR processes not occurring in HECTARE-METER surface impoundments or										gical treatment curring in tanks.		LITERS	PER D	AY		
			LICATION	D81 ACRES	E-METER OR HECTAR SPER DAY			ators	. Desc	∹b€ :	iments or inciner- the processes in ed; Item III-C.)						
ŀ			SPOSAL IMPOUNDMENT	LITERS	ER DAY			the o	pace p.	5010	,						
				UNITOF							IT OF						TOF
UΝ	HT (	OF M	EASURE	MEASURE CODE	UNIT	F ME	ASURE				ASURE ODE UN	IT OF M	EASURE				SURE
							DAY						T Meter.				
	BIC	YAI	RDS	<b>Y</b>			S PER I				. W AC	RES					. В
			PER DAY OR COMPLETIN				HOUR.					nks. one i	tank can h	old 200	) gallo	ns and	d the
othe				he facility also has an in								·, - · · ·					
5 C			DUP	13 14 15		7	$\overline{1}$	/		/				7	$\overline{/}$		
띥		PRO	B. PRO	CESS DESIGN CAPA		١,	FOR	ER	A. PR		B. PROCESS	DESIG	N CAPA				OR
MBE	CC	ESS		I. AMOUNT	2. UNI OF MEA SURE	OF	FICIAL USE	. [ 00 ]	CES COD (from	Ε	1. AM	GUNT.		OF	JNIT MEA- JRE	Ĺ	ICIA JSE
NIN NO M		m lis: ove)		(specify)	(enter		NLY	NCN	above					(e)	nter (de)	Ö	NLY
	16	- 11	19		27 28	25	- 32	1	16	18 1	9	-		27	28	29	3
X-1	_	0 2		600	G	++		5		+				$\dashv \dashv$	-		
X-2	T	0 3		20				6		+							+
1	s	0 1		154,000	ט			7		-							1
2	s	0 2	2	25,000	U		$\bot$	8		_							
3	Т	0 4	1	154,000	U		$\perp \mid$	9					,				
4	ل	بلب	1,2		27	29	ــلـــــــــــــــــــــــــــــــــــ	10	15	15 1	19			27	23	29	

III. PROCESSES (continued)

a second all and a line C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR CONTRIBUTION OTHER PROCESSES (code "TV4"). FOR MICH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

> Liquid and Semi-solid wastes are picked up from originator and hauled to a enclosed facility for treatment. Treatment will be either physical by addition of vermiculite or chemical for neutralization and solidification. Treated substances are then transported by a certified hauler to a certified disposal Some soiled solvents are transported to a solvent recovery facility.

## IV. DESCRIPTION OF HAZARDOUS WASTES

- A. EPA HAZARDOUS WASTE NUMBER Enter the four-digit number from 40 ) hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s! that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate

ENGLISH UNIT OF MEASURE CODE	METRIC UNIT OF MEASURE	CODE
POUNDS	KILOGRAMS	K
TONS. ,	METRIC TONS	M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

## D. PROCESSES

- 1. PROCESS CODES:
  - For listed hazardous waste: For each listed hazardous waste entered in column A select the code/s/ from the list of process codes contained in Item III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed hazardous wastes. For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

bte: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the treme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER - Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

- 1. Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B.C. and D by estimating the total annual
- quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.

  2. In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter 'included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

EXAMPLE FOR COMPLETING ITEM IV (shown in line numbers X-1, X-2, X-3, and X-4 below) - A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill


		A. EPA					C. UNIT		L	D. PROCESSES												
LINE NO.	W	AS	ST	E١	D. (O)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	S	SURE (enter code)				1. PROCESS CODES (enter)							DES	!	•	2. PROCESS DESCRIPTION (if a code is not entered in D(1))
X-1	K		0	5	4	900		P		Т	1	) 3	3	D	8	0		T	T	7		
X-2	L	)	0	0	2	400		P		T	7	0 3	3	D	8	0		Т	T	7		
X-3	L	) (	0	0	1	100		P		T	0	) 3	3	D	8	0		T		Т		
X-4	I		0	0	2						T				1	1		1	T	i	7	included with above

Continued from page 2. m Approved OMB No. 158-S80004 NOTE: Photocopy this page before completing if you have than 26 wastes to list. FOR OFFICIAL USE ONLY EPA I.D. NUMBER (enter from page 1) W , DESCRIPTION OF HAZARDOUS WASTES (continued) C.UNIT OF MEA-SURE D. PROCESSES A. EPA HAZARD B. ESTIMATED ANNUAL QUANTITY OF WASTE ZO WASTENO (enter code) 1. PROCESS CODES (enter 27 - 29 27 - 29 27 36 9 1 Т T 04 11440 sol P 0 01 2 P 1 22 8800 Т SO2 TOl U 0 01 3 **TO4** 2 39 18870 Т sol U U 0 01 2 3|9 14520 TOL SO2 U K 0 02 5 TO4 K 0 69 12580 т sol ĸ 0 02 6 K 0 69 968¢ SO2 TOL F 0 01 7 F 0 16 т sol TO4 14300 F 0  $q_1$ 0 Т S02 TOL F 16 11000 9 10 Note: 11 No Explosives No nuclear 12 wastes 13 14 15 17 18 19 20 21 23 24 25 26 EPA Form 3510-3 (6-80)


EPA Form 3510-3 (6-80)


PAGE 4 OF 5

**CONTINUE ON PAGE 5** 



Municipal Environmental Associates, Inc.









South Side









Iast Side












North Side

FECEIVED
R. FERMITS & PESTIGIDES SECT

DEC 2 2 1982


EPA, R3





South Side











Municipal Environmental Associates, Inc.



North Side

